

**BACCALAURÉAT PROFESSIONNEL
SECTION EUROPÉENNE
SESSION 2021**

*Maintenance des véhicules option B
Véhicules transport routier*

Épreuve orale spécifique de langue vivante : ANGLAIS

Entretien :

Partie A – 10 minutes

(à partir du sujet ci-dessous)

Partie B – 10 minutes

(entretien à partir des travaux et activités effectués pendant l'année de terminale dans la discipline non linguistique et ouverture européenne)

Durée de l'épreuve : 20 minutes

Préparation : 20 minutes

SUJET n° 1

<http://images.google.uk>

Situation:

You are a mechanic working at M50 Truck&van centre in Dublin, Ireland. You take charge of Mr. Scheffield who drives into the garage with his lorry. The lorry is a 440 Trakker IVECO.



He explains that the lorry didn't pass the MOT test. The lorry stays in low position and the ECAS light (suspension failed) is on, on the dashboard.


You ask Mr. Scheffield to drive the lorry into the workshop.

Your Tasks

- 1) Say what the possible causes of suspension failed are. (Use document 1 page 2/2)
- 2) You have checked the vehicle and you note that there is an air leak on the right level sensor. (Document 2 page 2/2)
Explain what the level sensor is for and how it works?
- 3) Explain what PPE you must wear and what precautions you must take before working on the lorry.

<http://images.google.uk>

- 1 : controlled pressure valve
- 2 : pressure switch
- 3 : air cushion
- 4 : level sensor
- 5 : electro-pneumatic dispenser
- 6 : air tank
- 7 : drain cap



IVECO : 04120 0708 - 004120 0708 - 0 4120 0708 - 4120 0708
SCANIA : 2 110 474 - 1 934 585 - 1 448 082
MAN : 81.25937.0040 - 36.25937.0000
DAF : 1524 843

Références équivalentes :

FEBI BILSTEIN : 27019
NIPPARTS : J1145006
NPS : M113118
PNEUMATICS : PN-10077 - PN-10056

<http://Febibilstein.com>

